

## FRS Logger: LogView setup

Here a brief overview how to setup LogView to create charts from your flight log data.

1. Load the LogView program from the LogView homepage and install it  
<http://www.logview.info/vBulletin/downloads.php>
2. Download the OpenFormat.ini file from my download page  
<http://www.hapeweb.com/download.html>  
  
and store it into the following folder :  
[http://www.logview.info/vBulletin/content.php?56-tips\\_1&s=b449ee70fe8412c29a612a4c41e25728](http://www.logview.info/vBulletin/content.php?56-tips_1&s=b449ee70fe8412c29a612a4c41e25728)
3. Download the file 'FRS\_LogView.lov' from my download page, start LogView and load the file. This is the template, showing all log data entries from the FRS\_Logger logged data.
4. In LogView click: 'Device' -> 'Choose device and port' and select 'OpenFormat/ FRS\_Logger' from the device list.
5. In LogView click: 'File' -> 'Import Devicefile...' and select the logged flight data ( OF Format ) to display it.  
Select the data you want to see, adjust the axis min/max Values and the graphs itself to get an optimal drawing
6. Enjoy it.



